cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



										/	
Intersection ID: 15235	Main Street: IDEAL_WY			Cross	Cross Street: IVERSON_WY				Location:	NE	
ADA ID: 016BD361A797	Ramp T	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	3 1 1 1 1	Possible Solutions:							Compliance Description Data		
	1	Remove & Replace Ent	iro Dan	an	N/A	Ramp Length (in)	168.0	N/A	Grade Break?	N/A	
				np.	Yes	Ramp Width (in)	57.0	N/A	Grade Break Slope (%)	0.0	
5 5	1 State				No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.0	
	7 1 1	4			No	Ramp XSlope (%)	3.3			••••	
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A state and a stat					N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	0.0	
Land W	GE	Surveyor Notes:			N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A	
	M.	STOP SIGN & FLASHIN		1.4.1	N/A	Landing Length (in)		N/A	DWS Provided?	N/A	
		STOP SIGN & FLASHIN		NAL	N/A	Landing Width (in)	0.0		DWS Contrast?	N/A	
		1			N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A	
The same		0-000			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	- AL	PROW/ADA:			N/A	Landing Curb? (Y/N)		N/A	DWS Offset LT (in)	N/A	
					N/A	Shared Landing?	N/A		DWS Offset RT (in)	N/A	
KING ME N	- Carol	R304.2.2, R304.5.3			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A N/A	
	E A-E				N/A	0	0.0		,	N/A N/A	
				N/A	Gutter Lip Ht (in) Painted X Walk1?	0.0 No	N/A	Gutter X Slope (%)	N/A 2.0		
		3			N/A				Road Slope (%)	-	
Street 1 Name	IDEAL WY					X Walk 1 Direction	To S		Road X Slope (%)	5.1	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A	N// A	Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	5.1	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	1.7	

