

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

55.5

32.0

8.0

2.1

5.1

3.4

N/A

No

N/A

1.9

3.1

N/A

N/A

To SE

Intersection ID: 9406 Main Street: CONDON_ST Cross Street: OAKLAWN_AV Location: NW

ADA ID: 017B2DC790A8 Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

No

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

58.0

31.0

7.3

6.0

25.0

45.0

N/A

No

N/A

3.2

1.5

N/A

4.2

To SW



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None
OAKLAWN AV
StopSign
CONDON ST

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3

Total Cost:

N/A Ramp Length LT (in) No Ramp Width LT (in) Yes Ramp Slope LT (%) Ramp XSlope LT (%) No N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction

N/A

Compliance Description

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)



3200.00

Road X Slope (%) 1.1 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 16.2 Curb Slope (%)



