

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19169Main Street:LIVINGSTON\_DRCross Street: SARDIS\_RDLocation:NWADA ID: 01C49156C9AARamp Type:PerpInitial Pass/Fail:FailOverall Compliance: NoSeverity Score:13.75

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name	LIVINGSTON DR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	9
Remove & Replace Entire Ramp.	
•	Υ
	N
	N
	1
	1
Surveyor Notes:	1
N/A	1
	1
	1
	1
PROW/ADA:	1
Not Found, R304.2.2, R304.5.3	N
	ı
	N
	N

e e e		
Na la		The la



Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	11.6		
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.3		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		