cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10034592	0: 10034592 Main Street: PIPER_STATION_DR Ci				oss Street: N/A				SE
ADA ID: 01E388CB0072	2 Ramp Type: BlendTrans1 In			ial Pass/Fail: Pass Overall Compliance: No				Severity Score:	0.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	e.	Possible Solutions:		Compliance Description Da			a Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	65.5	Yes	BlendTrans Slope (%)	4.3
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.8
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				Yes	Flare Slope LT (%)	2.2	N/A	Flare Slope RT (%)	9.0
		6		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
Sale Sale				Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Sales of the second sec		Surveyor Notes:		Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
		N/A		No	Landing Slope (%)	2.8	Yes	DWS Length (in)	24.0
				No	Landing X Slope (%)	3.0	Yes	DWS Full Width?	Yes
				N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
1.		4		N/A	Shared Landing?	No			
4		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.8
The second		R304.5.3, R304.2.2-Perp, R304.3.2-		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
5 6		Para		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
1 2 2 4					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	1 Marsha				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	_			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	3.9
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	2.7
Street 2 Name	PIPER STATION DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	1.5		Clear Space?	Yes
					Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good







N/A

Curb Slope (%)

2.3