

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Internetion ID: 50774 | | 0 | | | | Lesstians | 05 |
|---|--|--|--------------------------|------|-----------------|-----------------------------|------|
| Intersection ID: 52771 Main S | Main Street: DESIGNER_DR | | Cross Street: OUTLETS_BV | | | Location: | SE |
| ADA ID: 0394F34D6FD3 Ramp Type: Perp | | Initial Pass/Fail: Fail Overall Compliance: No | | | Severity Score: | 13.75 | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | | | | | |
| | Possible Solutions: | Compliance Description Data Co | | | Comp | liance Description | Data |
| | Remove & Replace Entire Ramp. | N/A | Ramp Length (in) | 96.0 | No | Ramp Slope (%) | 8.4 |
| | | Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 2.4 |
| | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | 2 | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | 10. | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | Surveyor Notes: | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Not Found, R304.2.2 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | | X Walk 1 Direction | To W | | X Walk 2 Direction | N/A |
| | 6 | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name DESIGNER DE | ł. | | X Walk 1 Slope (%) | 2.8 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 Non | • | | X Walk 1 X Slope (%) | 2.9 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name N/ | N Contraction of the second seco | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 N/ | N Contraction of the second seco | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Total Cost: \$1 | 850.00 | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

