cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



								N
Intersection ID: 30272	Main Street: CHALLENGER_DR		Cross Street: OLD_IRONSIDE_DR				Location:	N
ADA ID: 03BD4B047DB0	B047DB0 Ramp Type: BlendTrans1		nitial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
E E	Remove & Replace Curb Ran	np With	N/A	Ramp Length (in)	45.0	Yes	BlendTrans Slope (%)	2.4
	Two New Directional Ramps	or	Yes	Ramp Width (in)	52.0	No	BlendTrans XSlope (%)	7.5
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A A A A A A A A A A A A A A A A A A A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the state of the s	A De A		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second s	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A ANT AL	1.0		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second se			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name CHALLE	ENGER DR			X Walk 1 Slope (%)	6.1		X Walk 2 Slope (%)	0.9
Stop Condition-Street 1	None			X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	7.1
Street 2 Name OLD IRO	ONSIDE DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign			Road Slope (%)	6.8		Clear Space?	N/A
				Road X Slope (%)	6.0	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

15.0