

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18153	Main Street: BAYLOR_DR			Street:	GILMORE DR	Location:	S			
ADA ID: 03C9B78EFDB5 Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	A COMPET	Possible Solutions:		Compliance Description			Data Compliance Description		Data	
	1982 (Q	Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)	33.0	N/A	Grade Break?	N/A	
The states	and the second s			Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0	
	SA Stor			Yes	Ramp Slope (%)	4.6	N/A	Grade Break XSlope (%)	0.0	
	Re alto			No	Ramp XSlope (%)	2.6				
CILITO	A State - C	A		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
CORE OF	111			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
E E		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	and the second	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	a set main	k.		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
83	ALC: CHE	4		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
54		2		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	-	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	AN ANA	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	THE .	1		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
A AND AND AND AND AND AND AND AND AND AN	and the start			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	9.1	
Street 1 Name	BAYLOR DR				X Walk 1 Direction	To W		Road X Slope (%)	5.1	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	9.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.1	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	15.9	

