cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11089 Main Street: BREEDERS_CUP_CR			Cross	Cross Street: TRAVERS_RUN_DR				Location:	SW
ADA ID: 0496A7DA0C15	6A7DA0C15 Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	18.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
a hard a state of the		Remove & Replace Curb F	no With	N/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	2.4
		Two New Directional Ramps		No	Ramp Width (in)	35.0	No	BlendTrans XSlope (%)	2.8
CLE I		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
CUP_OR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E INTERNET		N/A		N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		Dive Onset (iii)	N/A
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			•		8			• • • •	N/A N/A
	1 Topland	Not Found, R304.5.1, R304.5	.3	N/A	Gutter Lip Ht (in)		N/A	Gutter X Slope (%)	
				N/A	Painted X Walk1?	No — N	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	TRAVERS RUN DR				X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.8		Clear Space?	N/A
					Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.1