## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18800 Main Street: PARK_RD Cross Street: SENECA_PL Location: SE								
Intersection ID: 18800 Main St	Main Street: PARK_RD		Cross Street: SENECA_PL				SE	
ADA ID: 054D8C4B9E05 Ramp T	Ramp Type: BlendTrans2		nitial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	ith N/A	Ramp Length (in)	92.0	Yes	BlendTrans Slope (%)	4.7	
		No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	6.2	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	4	N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
			X Walk 1 Direction	To N		X Walk 2 Direction	To W	
			X Walk 1 Width (in)	110.0		X Walk 2 Width (in)	120.0	
Street 1 Name SENECA PL			X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	0.2	
Stop Condition-Street 1 Signal			X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	3.0	
Street 2 Name PARK RD		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes	
Stop Condition-Street 2 Signal			Road Slope (%)	3.9		Clear Space?	N/A	
			Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

14.6