

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

3.0

1.2

N/A

Intersection ID: 17742 Main Street: S WENDOVER RD **Cross Street: PROVIDENCE RD** Location: SW ADA ID: 05B301E704D1 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Type LT

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

39.5 Yes

N/A N/A

116.0

Yes

Data Compliance Description

BlendTrans Slope (%)

BlendTrans XSlope (%)

Flare Type RT



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Restripe Crosswalk.





The series of	\2 6			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
0 1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
西西				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
* \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	West Control	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon	S S S S S S S S S S	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Sel -			N/A	Shared Landing?	N/A			
ON		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.1		N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	A 200				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
1/2					X Walk 1 Width (in)	103.0		X Walk 2 Width (in)	N/A
treet 1 Name	S WENDOVER RD				X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A
top Condition-Street 1	Signal				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
treet 2 Name	N/A			N/A	Ramp inside XWalk1?	No	N/A	Ramp inside XWalk2?	N/A
top Condition-Street 2	N/A				Road Slope (%)	3.9		Clear Space?	N/A
					Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3400.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good
							N/A	Curb Slope (%)	4.9