

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026308 Main Street: FAIRVIEW_RD Cross Street: N/A Location: SW **Severity Score:** Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 063A0D6F10C7 Ramp Type: Perp 22.5

Codes/Mitigation Info/Possible Solution



| | COLUMN TO THE REAL PROPERTY. |
|-------------------------|------------------------------|
| Street 1 Name | ENTRANCE |
| Stop Condition-Street 2 | None |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| Possible Solution | |
|-------------------------------|-----|
| Possible Solutions: | Con |
| Remove & Replace Entire Ramp. | N/A |
| | No |
| | N/A |
| | N/A |
| | N/A |
| | N/A |
| Surveyor Notes: | N/A |
| N/A | N/A |
| | N/A |
| | N/A |
| | N/A |
| PROW/ADA: | N/A |
| R304.5.1, R304.2.2 | N/A |
| , | N/A |
| | N/A |
| | N/A |

| Total Cost: | \$ 1850.00 |
|-------------|---------------|

| Field Measurements/Component Compliance | | | | | | | |
|---|-----------------------|-------|------|--------|-------------------------|------|--|
| Comp | liance Description | Data | Comp | liance | Description | Data | |
| N/A | Ramp Length (in) | 48.0 | No | Ram | Slope (%) | 10.8 | |
| No | Ramp Width (in) | 39.0 | Yes | Ram | XSlope (%) | 3.0 | |
| N/A | Flare Type LT | N/A | N/A | Flare | Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS | Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutte | er Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Paint | ed X Walk2? | N/A | |
| | X Walk 1 Direction | To SE | | X Wa | lk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Wa | lk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 2.1 | | X Wa | lk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 3.4 | | X Wa | lk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ram | inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear | Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear | Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storn | n Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storn | n Grate/Utility Type | | |
| | | N/A | | | | N/A | |
| | | | Yes | Surfa | ce Condition? (G/P) | Good | |
| | 9 | | | | | | |





