

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22011	2011 Main Street: SOUTH_BV				Street:	HILL_RD	Location:	SE		
ADA ID: 064963B54D4E					Initial Pass/Fail: Fail Overall Compliance: No					17.5
· · · ·			minutar	1 455/1			17.0			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance Compliance Description Data						
		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Ent	tire Ramp).	N/A	Ramp Length (in)	59.0		Ramp Slope (%)	5.2
蜜儿、蜀口子吗					No	Ramp Width (in)	35.0		Ramp XSlope (%)	0.8
	Comments of the second				N/A	Flare Type LT	N/A		Flare Type RT	N/A
	Charles Chir .				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
	6.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	CITU PD				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	COLUMN AND	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A					N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	A A PARTY A TO MARKED AND	6			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Marke 1	ame Inthing				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	a contraction of the				N/A	Shared Landing?	N/A			
PROW/ADA:					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A CONTRACTOR OF						X Walk 1 Direction	To N		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HILL RD					X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
		-	•			21	N/A			N/A
								1		

Yes Surface Condition? (G/P)

Good

