cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10029688	029688 Main Street: KINGSLEY_VIEW_DR			Cross Street: N/A				Location:	W
ADA ID: 07295DF3E3CC	E3CC Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	11561539	Possible Solutions:		Compliance Description Data Complian			liance Description	Data	
	6.69	Remove & Replace Curb R	n With	N/A	Ramp Length (in)	57.0	Yes	BlendTrans Slope (%)	3.1
		Two New Directional Ramps o		No	Ramp Width (in)	44.0	Yes	BlendTrans XSlope (%)	1.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A		DWG Oliset (iii)	11/2	
PROW/ADA: Not Found, R304.5.1				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	-	N/A	N/A		N/A N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in) Painted X Walk1?		N/A	Gutter X Slope (%) Painted X Walk2?	N/A No
				N/A			N/A		-
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
	SLEY VIEW DR				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	5.8
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	5.7		X Walk 2 X Slope (%)	2.8
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	2.7		Clear Space?	N/A
					Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.9