cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44459	Main Sti	Main Street: AMES_HOLLOW_RD			Cross Street: OVERLAY_CT				E
ADA ID: 084DA6B378A7	Ramp Ty	Ramp Type: BlendTrans1			ail: Fail Overall	ice: N	o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da				Data	
		Remove & Replace Curb Ra	mp With	N/A	Ramp Length (in)	47.5	Yes	BlendTrans Slope (%)	3.3
		Two New Directional Ramps		No	Ramp Width (in)	46.0	Yes	BlendTrans XSlope (%)	1.6
		Equivalent.	•	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		5		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
a b		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Collo			N/A	Shared Landing?	N/A			
	A A A A A A A A A A A A A A A A A A A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
19/1		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
and the second second	12YEAN				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	OVERLAY CT	-			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	1.8
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	2.8
Street 2 Name	AMES HOLLOW RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	0.8		Clear Space?	N/A
	itono				Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	11/2	Obstruction Type	174		Storm Grate/Utility Type	19/5
		φ	0200.00			N/A		Storm Orace Ouncy Type	N/A
						IN/A			11/74







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.2