

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28182	Main Street: FIELDCROFT_DR			Street:	WOODEND_CT	Location:	SW		
ADA ID: 0867ED082139	Ramp Ty	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
	6. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	92.0	Yes	BlendTrans Slope (%)	2.8
		Two New Directional Ramps or		No	Ramp Width (in)	44.0	No	BlendTrans XSlope (%)	3.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		1071		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
A A A A A A A A A A A A A A A A A A A		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second s				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	carl and				X Walk 1 Direction	To E		X Walk 2 Direction	To N
A S. A	Contraction of				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	FIELDCROFT DR	-			X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	2.1
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	0.5
Street 2 Name	WOODEND CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	1.1		Clear Space?	N/A
	. • 5				Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.6