

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6565	Main Street: DAVID_EARL_DR			Cross	Cross Street: OREN_THOMPSON_RD				Location: E		
ADA ID: 0A0AC80CAD3F Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No					22.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description			
10 1 1 - 1		Remove & Replace En	itire Ram	р.	N/A	Ramp Length (in)	60.0	N/A	Grade Break?	N/A	
	The second				No	Ramp Width (in)	44.0	N/A	Grade Break Slope (%)	0.0	
	AL AL				No	Ramp Slope (%)	9.3	N/A	Grade Break XSlope (%)	0.0	
	1 1 12 -1				No	Ramp XSlope (%)	2.5				
AND MERIO	ALL CONTRACT				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
MOSCHIONIC VERIO					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	<u>10</u>	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	In the second second				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	Philippine The set				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	1	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
PROW/ADA: R304.5.1, R304.2.2, R304.5.3					N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
the second of the second					N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	the states				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No		Road Slope (%)	0.4	
Street 1 Name	DAVID EARL DR					X Walk 1 Direction	To W		Road X Slope (%)	2.6	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.6	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	17.1	

