cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: SENECA_PL		Cross Street: N/A					Location:	NE
ADA ID: 0A7D4589F95C	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
E Contraction of the second se	F	Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	110.0	Yes	BlendTrans Slope (%)	2.9
		Two New Directional Ramps or		No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	6.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	in the second se	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
STATE 5		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6	Server and			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second	Can Batt			N/A	Shared Landing?	N/A			
	- Mary	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The Share the star	ER			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	1				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
7 2 2 2 2 2					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	SENECA PL	-			X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	4.2		Clear Space?	N/A
					Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

20.0