cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8793	Main Street: BARRINGTON_DR			treet:	WOODFIELD_DR	Location:	SW		
ADA ID: 0B883B427D23	Ramp Type: BlendTrans2			nitial Pass/Fail: Pass Overall Compliance: N				Severity Score:	: 7.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	25.5	Yes	BlendTrans Slope (%)	5.0
		Two New Directional Ramps or Equivalent. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: Not Found, R305.2, R302.7,	-	Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.6
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				N/A	Flare Slope LT (%)	3.9	N/A	Flare Slope RT (%)	3.7
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
				N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
				N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
the state of the s				N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.5
				N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0
	1 Martin			N/A	Shared Landing?	No	-		
				No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	1.3
	a total and the			No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	3.8
Street 1 Name WOODFIELD DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	0.0 N/A
		1002.7.2, 1004.0.0		1/7	X Walk 1 Direction	To SE	10/2	X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A N/A
				()					
					X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.4	N//A	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.4		Clear Space?	Yes
					Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 3	950.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

 Yes
 Surface Condition? (G/P)

 No
 Curb Slope (%)

Good

21.4



