

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54318 Main Street: CANTERBURY_CASTLE_DR Cross Street: BELMONT_MANSION_DR Location: NW **ADA ID: 0FDF0407DA31** Ramp Type: BlendTrans1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED
Street 1 Name	CANTERBURY CASTLE DR
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

GGG:BIG GGIATION
Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.1, R304.5.3

1	

Total Cost:



3200.00

Field Measurements/Component Compliance								
Compliance Description		Data	Compliance Description		Data			
N/A	Ramp Length (in)	95.0	Yes	BlendTrans Slope (%)	1.6			
No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	6.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A			
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	1.1		Clear Space?	N/A			
	Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
			No	Curb Slope (%)	7.6			
			-					