

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30378	Main Str		P	Cross	Stroot.				Location:	SE	
	Main Street: VERNEDALE_GLEN_DR				Cross Street: WILORA_LAKE_RD						
ADA ID: 12EF64B3E806 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	a series and	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
6	State of	Remove & Replace Entir	e Ram	р.	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	12.0	
A A A A A A A A A A A A A A A A A A A					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3	
and the second	H. AN				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Real Room	1 and the				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	a state				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A REAL PROPERTY				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
the second se	N. Balance	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
2 the second sec	4354	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the second secon					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	Marking Long				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
a second	No I To	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
F" I	1 111 3	Not Found, R304.2.2, R3	04.5.3		N/A	Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A	
Lin PI	A LAND				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
in the second					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	WILORA LAKE RD					X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	