

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15102	Main Str	Main Street: QUEENS_RD			Cross Street: E_MOREHEAD_ST				SW
ADA ID: 130EECA6EAA8	Ramp Ty	ype: BlendTrans1	Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A STATE AND A STATE OF		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	65.5	Yes	BlendTrans Slope (%)	3.8
		Two New Directional Ramps or		No	Ramp Width (in)	47.0		BlendTrans XSlope (%)	2.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
	6	Surveyor Notes:		N/A	Landing Length (in)	N/A		DWS Provided?	N/A
S SILLION OF	i.			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
EDCEJILL-June		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		DWG Oliset (III)	N/A
The second s					•	N/A	N/A	Cuttor Clana (0/)	NI/A
		PROW/ADA:		N/A	Gutter Ponding?			Gutter Slope (%)	N/A
	14. M	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
					X Walk 1 Width (in)	113.0		X Walk 2 Width (in)	83.0
Street 1 Name	QUEENS RD				X Walk 1 Slope (%)	9.0		X Walk 2 Slope (%)	8.2
Stop Condition-Street 1	Signal				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	6.8
Street 2 Name	E MOREHEAD ST			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 2	Signal				Road Slope (%)	2.8		Clear Space?	N/A
					Road X Slope (%)	11.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

25.3