cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27626	27626 Main Street: FLORAL_HALL_DR			Cross Street: JAMES_JACK_LN				Location:	SW
ADA ID: 132E69D03187	Ramp Type: BlendTrans2			tial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	is is the second s	Possible Solutions:		Compliance Description		Data	ata Compliance Description		Data
A A		Remove & Replace Curb Ramp V Two New Directional Ramps or Equivalent.	mn With	N/A	Ramp Length (in)	53.0	Yes	BlendTrans Slope (%)	1.6
			•	No	Ramp Width (in)	43.0		BlendTrans XSlope (%)	2.8
				N/A	Flare Type LT	N/A		Flare Type RT	N/A
FLORAL MALL DR				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E I				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		174		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.	53	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Not i ound, 1004.0.1, 1004.	.0.0	N/A	Painted X Walk1?	No		Painted X Walk2?	N/A	
PROW/ADA: Not Found, R304.5.1, R304.5.3					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	JAMES JACK LN				X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.6		Clear Space?	N/A
					Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		·			<i>,</i> ,	N/A			N/A
							1		

YesSurface Condition? (G/P)NoCurb Slope (%)

Good

21.8





