cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Curb Slope (%)

18.6

Intersection ID: 15512	ntersection ID: 15512 Main Street: MARSH_RD		Cross Street: MELBOURNE_CT			Location: V		W
ADA ID: 13B692DA0883	Ramp Type: Combination2Diag		tial Pass/Fail: Fail Overall Compl		omplian	Ince: No Severity Score:		0
Codes	Field Measurements/Component Compliance							
		Compliance Description D		Data	Data Compliance Description		Data	
	Remove & Replace	Curb Ramp With	N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	51.0
	Two New Direction		N/A	Ramp Width LT (in)	N/A	Yes	Ramp Width RT (in)	59.0
	Equivalent.	•	N/A	Ramp Slope LT (%)	N/A	No	Ramp Slope RT (%)	8.7
	CHART -		N/A	Ramp XSlope LT (%)	N/A	No	Ramp XSlope RT (%)	3.4
			N/A	Ramp Length (in)	24.5	Yes	Ramp Slope (%)	6.0
Kan Kan			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2
P G	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
dia dia			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A CAR AND A			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
a design of the second s	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Not Found, R304.3.	2. R304.5.3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ALL STATE		,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	m la serie		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	MELBOURNE CT		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None			X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
Stop Condition-Street 2	MARSH RD			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	3.8
				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	2.0
	Total Cost:	\$ 3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	1.7		Clear Space?	N/A
				Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A
				A REAL PROPERTY AND A REAL PROPERTY AND A REAL PROPERTY A REAL		N/A	Any Obstruction?	N/A
	合合						Obstruction Type	
								N/A
			and the second			N/A	Storm Grate/Utility Hazard?	N/A
		Server St.					Storm Grate/Utility Type	17/5
								N/A
						Yes	Surface Condition? (G/P)	Good