

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	•				· //	
Intersection ID: 13760	Main Str	Main Street: EUCLID_AV		Cross Street: TEMPLETON_AV				Location:	W
ADA ID: 144EE96C0414	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A A A A A A A A A A A A A A A A A A A		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
2 1 1 1 3 1	A Start Start	Remove & Replace Entire Ra	np.	N/A	Ramp Length (in)	48.0	N/A	Grade Break?	N/A
and all and a		•	•	No	Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0
	and the second			Yes	Ramp Slope (%)	7.4	N/A	Grade Break XSlope (%)	0.0
	A CAL			No	Ramp XSlope (%)	2.4			
	A la			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
હાર		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
J. A.		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
5	the second			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	CARA L			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
EUG:	· State			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	Ing al	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A PT ST AND	2 * 1 Pag 20	R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Ang 1 a gent	····, ····		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
and the second of the	134 244			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	1 Ach			N/A	Painted X Walk1?	No		Road Slope (%)	10.4
Street 1 Name	TEMPLETON AV				X Walk 1 Direction	To NE		Road X Slope (%)	1.0
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	10.4	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.0	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	6.0

