cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

1.1

Intersection ID: 20325	D: 20325 Main Street: CREOLA_RD			Cross	Street:	PROVIDENCE_RD	Location:	SE		
ADA ID: 153A8A88F87D	A8A88F87D Ramp Type: ParaDiag			Initial	Pass/Fa	ail: Fail Overal	o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	States	Possible Solutions:			Compliance Description		Data Compliance		liance Description	Data
12 1 - 15-		Remove & Replace Curb	Ram	o With	N/A	Ramp Length LT (in)	47.0	N/A	Ramp Length RT (in)	42.0
		Two New Directional Ram		•	Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	63.0
		Equivalent.			No	Ramp Slope LT (%)	9.0	Yes	Ramp Slope RT (%)	6.0
					Yes	Ramp XSlope LT (%)	0.5	No	Ramp XSlope RT (%)	2.6
	and the second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E GREOLA RD					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Seal S	Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E Contraction		N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	- in				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1.7.	PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.3.2, R304.5.3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		,				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	2.8
Street 1 Name	CREOLA RD					X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	4.1
Stop Condition-Street 1	StopSign				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name PRC	DVIDENCE RD					Road Slope (%)	0.9	N/A	Clear Space?	N/A
Stop Condition-Street 2	None					Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
						Obstruction Type			Storm Grate/Utility Type	
		Total Cost:	\$	3200.00			N/A			N/A
								Yes	Surface Condition? (G/P)	Good

