

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10020375 Main Street: BALLANTYNE_CORPORATE_PCross Street: N/A Location: NW

ADA ID: 159616721D15 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name ENTRANCE
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.3

Total Cost:





3200.00

| Compliance Description Data Compliance | |
|--|-------------------------------|
| Compliance Description Data Compliance | e Description Data |
| N/A Ramp Length (in) 108.0 Yes Blo | ndTrans Slope (%) 0.6 |
| Yes Ramp Width (in) 48.0 No Ble | ndTrans XSlope (%) 4.9 |
| N/A Flare Type LT N/A N/A Fla | re Type RT N/A |
| N/A Flare Slope LT (%) N/A N/A Fla | re Slope RT (%) N/A |
| N/A Flare Traversable LT? N/A N/A Fla | re Traversable RT? N/A |
| N/A Landing Length (in) N/A N/A DV | /S Provided? N/A |
| N/A Landing Width (in) N/A N/A DV | /S Contrast? N/A |
| N/A Landing Slope (%) N/A N/A DV | /S Length (in) N/A |
| N/A Landing X Slope (%) N/A N/A DV | /S Full Width? N/A |
| N/A Landing Curb? (Y/N) N/A N/A DV | /S Offset (in) N/A |
| N/A Shared Landing? N/A | |
| N/A Gutter Ponding? N/A N/A Gu | tter Slope (%) N/A |
| N/A Gutter Lip Ht (in) N/A N/A Gu | tter X Slope (%) N/A |
| N/A Painted X Walk1? No N/A Pa | nted X Walk2? N/A |
| X Walk 1 Direction To NE X | Valk 2 Direction N/A |
| X Walk 1 Width (in) N/A X | Valk 2 Width (in) N/A |
| X Walk 1 Slope (%) 2.9 X | Valk 2 Slope (%) N/A |
| X Walk 1 X Slope (%) 0.7 X | Valk 2 X Slope (%) N/A |
| N/A Ramp inside XWalk1? N/A N/A Ra | mp inside XWalk2? N/A |
| Road Slope (%) 0.7 Cle | ear Space? N/A |
| Road X Slope (%) 2.9 N/A Cle | ear Space to XWalk (in) N/A |
| N/A Any Obstructions? N/A N/A Sto | orm Grate/Utility Hazard? N/A |
| Obstruction Type Sto | orm Grate/Utility Type |
| N/A | N/A |
| Yes Su | rface Condition? (G/P) Good |
| N/A Cu | rb Slope (%) 3.0 |