

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44471	Main St	reet: COREY_COMMON_AV	Cros	ss Street	REDDING_GLEN_AV			Location:	NW
ADA ID: 16EEF839AE3C Ramp Type: BlendTrans1			Initia	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	8	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb R	amp With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	1.7
		Two New Directional Ramp		No	Ramp Width (in)	42.0	Yes	BlendTrans XSlope (%)	0.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 + + 1	R			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A 14 (B 14)		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
TUDES A THE	The second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
CUE			N/A	Shared Landing?	N/A				
Deliter		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
533		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Baarde 19				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	REDDING GLEN AV	_			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	1.0
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	1.3
Street 2 Name	COREY COMMON AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	0.9		Clear Space?	N/A
					Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.2