

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7023 Main Street: EASTER_LN Cross Street: MELYNDA_RD Location: **Overall Compliance: No Severity Score:** ADA ID: 174A6F0FF574 Ramp Type: Perp Initial Pass/Fail: Fail 12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name **EASTER LN** Stop Condition-Street 2 StopSign Street 2 Name N/A N/A Stop Condition-Street 1

Possible Solutions:	Col
Remove & Replace Entire Ramp.	N/A
	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
,	N/A
	N/A
	N/A

PROW/ADA:			N/A
Not Found, R304.2.2		N/A	
			N/A
			N/A
			N/A
Total Cost:	\$	1850.00	N/A



Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	48.0	No	Ramp	Slope (%)	8.6
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	1.3
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.1		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.5		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good