cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: 14556	Main Street: E_WORTHINGTON_AV			Street:	WINTHROP_AV	Location:	S		
ADA ID: 17631D536A6E	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	36.0	Yes	BlendTrans Slope (%)	3.6
		Two New Directional Ramps or		No	Ramp Width (in)	44.0	No	BlendTrans XSlope (%)	3.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E.S.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	5			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	E. C. Marker	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
L.E.	Ch .	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Lee .	1/2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A Star	CO MARCON COM			N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
	Con the second	PROW/ADA:		N/A	Shared Landing?	N/A		2110 011001 (11)	
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A second and a second	Not Found, R304.5.1, R304.5.3		N/A	Painted X Walk1?	No		Painted X Walk2?	N/A N/A	
				N/A	X Walk 1 Direction	To NE	IN/A	X Walk 2 Direction	N/A N/A
									N/A N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)		
Street 1 Name	E WORTHINGTON AV				X Walk 1 Slope (%)	7.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.0		Clear Space?	N/A
					Road X Slope (%)	7.6		Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.8