

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 25067 Main Street: CARRIAGE LAKE DR **Cross Street: SMITH RD** Location: NE ADA ID: 178C4E50685C Ramp Type: BlendTrans2 Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 2.75

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

**SMITH RD** None **CARRIAGE LAKE DR** 

StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.3, R305.1.4, R305.2

Total Cost: 3950.00

Field Measurements/Component Compliance						
Compliance Description			Data	Compliance Description		Data
ı	N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	0.5
,	<b>Yes</b>	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.3
ı	N/A	Flare Type LT	None	N/A	Flare Type RT	None
ı	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ı	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ı	N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
ı	N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
ı	N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
ı	N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
ı	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
ı	N/A	Shared Landing?	No			
,	<b>Yes</b>	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.8
`	es/	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.5
ı	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.9
		X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	0.7
ı	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.9		Clear Space?	Yes
		Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
,	<b>Yes</b>	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
	No.			No	Curb Slope (%)	30.8





