cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30344 Main Street: FOX SWAMP RD Cr						SANDBOAR_ST	Location:	SW		
ADA ID: 181BAA45378B Ramp Type: BlendTrans1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	18.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Comp	liance Description	Data Complian		liance Description	Data
YTER		Remove & Replace Curb Two New Directional Ran Equivalent.	rb Ram	p With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.6
			Ramps or	or	No	Ramp Width (in)	35.0	No	BlendTrans XSlope (%)	3.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
SAMDERAND	10 -				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ST ST - E	1				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second secon		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>د</u> //	Carlo March	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
3 / 1				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
Si Est	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not Found, R304.5.1, R304.5.3			R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To E		X Walk 2 Direction	To NE	
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name F	OX SWAMP RD					X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	5.0
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	1.1
Street 2 Name	SANDBOAR ST				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	1.6		Clear Space?	N/A
						Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.7