

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | Main Of | | 0 | | | • | | Lesstiens | 0 | |
|---|---------------------------------------|------------------------------|---------|---|-----------------------|-------|-----------------------------|-----------------------------|------|--|
| Intersection ID: 53288 | Main Street: PROSPERITY_CHURCH_RD | | | Cross Street: ROBERT_HELMS_RD | | | Location: S | | | |
| ADA ID: 18D396A6D070 | D070 Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliane | | | nce: N | o Severity Score: | 25 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | A BANK BE | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | | |
| | TIME RD | Remove & Replace Entire Ramp | | N/A | Ramp Length (in) | 96.0 | No | Ramp Slope (%) | 12.3 | |
| | OBERT MELMOS | | | Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 1.0 | |
| L | 6. | 4 | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | arnell a | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | Care Contraction | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | Maria . | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| The second se | -siete - ja | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | No. | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | | | N/A | Shared Landing? | N/A | | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | Yes | N/A | Gutter Slope (%) | N/A | |
| | | R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | E A LANGE | 2 | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | |
| | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 9 | | | X Walk 1 Direction | To W | | X Walk 2 Direction | N/A | |
| | | 2 | | N/A | X Walk 1 Width (in) | 100.0 | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name PROSPE | RITY CHURCH RD | | | | X Walk 1 Slope (%) | 2.3 | | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 2 | YieldSign | | | | X Walk 1 X Slope (%) | 1.9 | | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | | N/A | | | N/A | |

Yes Surface Condition? (G/P)

Good

