

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



	N//A			Lesstern	14/				
Intersection ID: 12385	Main Street: PAMLICO_ST			Cross Street: N/A				Location:	W
ADA ID: 192656F23D9E	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A STATE	Possible Solutions:		Compliance Description Data Complia			liance Description	Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.5	Yes	BlendTrans Slope (%)	4.6
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	37.0	No	BlendTrans XSlope (%)	2.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second se	Con Deers			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
a San Bry		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
e la	-ellin			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
and a start					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	PAMLICO ST				X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.2		Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

22.8