## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 3706	Main Street: PROSPERITY_CHURCH_RD			Cross Street: PROSPERITY_POINT_LN				Location:	S
ADA ID: 19BB3288BB4D	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description	
	THE OF	Remove & Replace Entire Ran	D.	N/A	Ramp Length (in)	37.5	Yes	Ramp Slope (%)	7.3
A BERTHERE	· Caller		•	Yes	Ramp Width (in)	49.5	No	Ramp XSlope (%)	2.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	213			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6 0				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
COLUTE FOR	A AC	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
TUNAC 6.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
13052				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	(KS)			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	M.			N/A	Shared Landing?	N/A			
	119	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 Y	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ST CALL				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	11/10				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	95.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name PROPERTY POINT LN					X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

