## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-		-					
Intersection ID: 27673	Main Str	eet: GUNPOWDER_POINT_DR	Cross	Cross Street: NOLEN_LN				Location:	SE
ADA ID: 1A2D014D228E	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	THE	Possible Solutions:		Comp	pliance Description		Comp	liance Description	Data
M		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	1.8
		Two New Directional Ramps or		Yes	Ramp Width (in)	50.0	No	BlendTrans XSlope (%)	8.0
	800	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
COTTOP-	9/ 5 - A 4			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E & CULL				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	-			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	HE CY	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
E.	A State of the second s			N/A	Shared Landing?	N/A			
	and the sea	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	the states	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Can Kinker				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	dt				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	A State				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	NOLEN LN				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	9.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	9.7		Clear Space?	N/A
					Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.1