

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28029 Main Stre	Main Street: BAY_HILL_CLUB_DR		Cross Street: PINE_VALLEY_CLUB_DR				SW
ADA ID: 1B4C1618BA99 Ramp Ty	9 Ramp Type: Perp		Initial Pass/Fail: Pass Overall Compliance: I			o Severity Score:	15
Codes/Mitigation Info/		Field Measurements/Component Compliance					
	Possible Solutions:			Data Compliance Description			Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	43.0	Yes	Ramp Slope (%)	5.1
	Remove & Replace Gutter.	Yes		48.0	Yes	Ramp XSlope (%)	0.9
	·	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	0.4	Yes	Flare Slope RT (%)	4.1
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
BAY HILL CLUB DR		No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
A DECISION DR B	Surveyor Notes:	No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
E B	N/A	No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
		No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0
		N/A	Shared Landing?	No			
	PROW/ADA:	No	Gutter Ponding?	Yes	No	Gutter Slope (%)	6.4
	Not Found, R304.2.1, R304.2.2-Pe	rp. Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
	R304.3.2-Para, R304.5.3, R302.7,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	R304.5.4		X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name PINE VALLEY CLUB DR			X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	Yes
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$ 26	500.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A
					Yes	Surface Condition? (G/P)	Good



