

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17276 Main Street: PINEWOOD_CR Cross Street: PROVIDENCE_RD Location: NW

ADA ID: 1C53D1B8C19C Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

PINEWOOD CR StopSign PROVIDENCE RD None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

No New Directional Ramps or
Equivalent.

No New Directional Ramps or
No New Direction Ramps or
No New Direction Ramps or
No New Direction Ramps or
No New Direc

Total Cost: \$ 3200.00

Fleid Measurements/Component Compilance						
	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	24.5	Yes	BlendTrans Slope (%)	3.2
	No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.3
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	5.8
		X Walk 1 X Slope (%)	7.1		X Walk 2 X Slope (%)	4.1
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	0.8		Clear Space?	N/A
		Road X Slope (%)	7.2	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
				N/A	Curb Slope (%)	1.3





