

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: MULLAN_LN			Cross Street: REALTA_DR					NW
ADA ID: 1CA941E9E450	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					10
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
atter the state of the	A set and a set of	Possible Solutions:	Compliance Description			Data	Data Compliance Description		
The state of the	1 mall	Remove & Replace Entire Ramp	N/A	Ramp Le	ngth (in)	96.0	Yes	Ramp Slope (%)	7.9
and the second second	in the		No	Ramp Wi		46.0	No	Ramp XSlope (%)	4.2
the same			N/A	Flare Typ	e LT	N/A	N/A	Flare Type RT	N/A
1 - I - I - IS			N/A	Flare Slo	pe LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	P. Ca		N/A	Flare Tra	versable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing L	₋ength (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N/A	Landing \	Vidth (in)	N/A	N/A	DWS Contrast?	N/A
REALTA DR	5.1	N/A	N/A	Landing S	Slope (%)	N/A	N/A	DWS Length (in)	N/A
REALERS	(F)		N/A	Landing >	K Slope (%)	N/A	N/A	DWS Full Width?	N/A
	6		N/A	Landing (Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared L	anding?	N/A			
		PROW/ADA:	N/A	Gutter Po	onding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip	o Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	E	,	N/A	Painted X	Walk1?	No	N/A	Painted X Walk2?	N/A
In the second		X Walk 1	Direction	To S		X Walk 2 Direction	N/A		
			N/A	X Walk 1	Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REALTA DR			X Walk 1	Slope (%)	3.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk 1	X Slope (%)	3.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp ins	ide XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slo	pe (%)	N/A	N/A	Clear Space?	N/A
				Road X S	lope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/4			N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstructi	on Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

