

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10023924Main Street: CONLAN_CRCross Street: N/ALocation:NADA ID: 1DC7100BD265Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:25

Codes/Mitigation Info/Possible Solution



Street 1 Name	CONLAN CR
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Com
Remove & Replace Entire Ramp.	N/A
	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.2.2	N/A
,	N/A
	N/A
	N/A

E.	THE RESERVE TO SERVE
	1



Total Cost:



1850.00

u33/1	an. ran Overan	Compilan	100. IN	o deventy ocore.					
Field Measurements/Component Compliance									
Comp	oliance Description	Data	Compliance Description		Data				
N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	13.4				
Yes	Ramp Width (in)	61.0	Yes	Ramp XSlope (%)	1.3				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	102.5	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type		l	Storm Grate/Utility Type					
		N/A			N/A				
			Yes	Surface Condition? (G/P)	Good				
MAJA 34000									