cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4727	Cross St	eet:	GREYSTONE_PARK_L	Location:	NW					
ADA ID: 1E48C3423A	423A51 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	(Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ramp W	-	I/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	<u>Data</u> 7.2	
		Two New Directional Ramps or Equivalent.		'es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.8	
				I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
ART A				/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
and the state of the		· ·		/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A N/A	
GREYSTONE_PARK_L		N/A			3 1 ()			DWS Length (III) DWS Full Width?		
CKEVOICIUL JANG		4		I/A	Landing X Slope (%)	N/A	N/A		N/A	
				I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
- Carlos	R		I/A	Shared Landing?	N/A					
		PROW/ADA:		I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
- Broat		Not Found, R304.5.3	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To S		X Walk 2 Direction	To E	
		N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	GREYSTONE PARK LN				X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	5.0	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.7		X Walk 2 X Slope (%)	2.9	
Street 2 Name	CARRINGTON FOREST LN		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	5.3	N/A	Clear Space?	N/A	
					Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	N/A	
			1	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
		•••••••••••••••••••••••••••••••••••••••				N/A			N/A	
						104	1			

Yes Surface Condition? (G/P)

Good

