cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11462	Main Street: STONEHAVEN_DR			Cross Street: TIPPERARY_PL				Location:	SE
ADA ID: 1FF8B1A46660	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	TONEL'AVEN DR	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Rar Two New Directional Ramps Equivalent.	Ramp With	N/A	Ramp Length (in)	78.0	Yes	BlendTrans Slope (%)	1.5
			•	No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	0.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
K Starten Star		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A Parto			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
a la	a provide			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A Company				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	STONEHAVEN DR	_			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	0.8
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	0.5
Street 2 Name	TIPPERARY PL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	0.2		Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

20.6