

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                             |                         |                        |
|------------------------|-----------------------------|-------------------------|------------------------|
| Intersection ID: 11730 | Main Street: MECKLENBURG_AV | Cross Street: THE_PLAZA | Location: NW           |
| ADA ID: 232BBC8BAA19   | Ramp Type: Para             | Initial Pass/Fail: Fail | Overall Compliance: No |
|                        |                             |                         | Severity Score: 13.75  |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**LT RP < 5%**

PROW/ADA:

**R304.5.3, R304.3.2**

Total Cost:

**\$ 1600.00**

| Compliance | Description          | Data  | Compliance | Description                 | Data |
|------------|----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)  | 73.0  | N/A        | Ramp Length RT (in)         | 64.0 |
| Yes        | Ramp Width LT (in)   | 60.5  | Yes        | Ramp Width RT (in)          | 58.5 |
| Yes        | Ramp Slope LT (%)    | 1.4   | No         | Ramp Slope RT (%)           | 10.8 |
| No         | Ramp XSlope LT (%)   | 5.0   | No         | Ramp XSlope RT (%)          | 2.8  |
| N/A        | Landing Length (in)  | N/A   | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)   | N/A   | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)    | N/A   | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)  | N/A   | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)  | N/A   | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?      | N/A   |            |                             |      |
| N/A        | Gutter Ponding?      | N/A   | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)   | N/A   | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?     | Yes   | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction   | To NE |            | X Walk 2 Direction          | N/A  |
| N/A        | X Walk 1 Width (in)  | 102.0 | N/A        | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)   | 1.0   |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%) | 2.0   |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?  | Yes   | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)       | N/A   | N/A        | Clear Space?                | N/A  |
|            | Road X Slope (%)     | N/A   | N/A        | Clear Space to XWalk (in)   | N/A  |
| N/A        | Any Obstructions?    | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            | Obstruction Type     |       |            | Storm Grate/Utility Type    |      |
|            |                      | N/A   |            |                             | N/A  |
|            |                      |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                      |       | N/A        | Curb Slope (%)              | 14.4 |

