## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28305	ersection ID: 28305 Main Street: COMMUNITY_HOUSE_RD Cross Street: TAMARACK_DR								Location: E	
· · ·				Initial						12.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions: Remove & Replace Curb Ram Two New Directional Ramps of Equivalent.			Compliance Description		Data	Data Compliance Description		Data
			•	o With	N/A	Ramp Length (in)	39.0	Yes	BlendTrans Slope (%)	3.3
				r	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.9
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
de the		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6. 6. 19 1 · · · · · · · · · · · · · · · · ·					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	21/1/201	Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
						X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
A	6. 1. 6 1 6 1 C					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	TAMARRON DR					X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	1.8
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	2.8
Street 2 Name	COMMUNITY HOUSE RD				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None					Road Slope (%)	2.4		Clear Space?	N/A
						Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.2