

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3233Main Street:HERITAGE\_HILLS\_LNCross Street:PROSPERITY\_CHURCH\_RDLocation:NWADA ID: 245ECF1C2B01Ramp Type:ParaInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name PROSPERITY CHURCH RD
Stop Condition-Street 1 None
Street 2 Name N/A
Stop Condition-Street 2 N/A

i ossible solution	
Possible Solutions:	
Remove & Replace Entire Ramp.	ľ
•	١
	١
	١
	ı
	N
Surveyor Notes:	M
N/A	ı
	N
	ı
	N
PROW/ADA:	N
R304.3.2, R304.5.3	ı
	ľ

Total Cost: \$ 1600.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length LT (in)	64.0	N/A	Ramp Length RT (in)	56.0		
Yes	Ramp Width LT (in)	71.0	Yes	Ramp Width RT (in)	71.0		
Yes	Ramp Slope LT (%)	7.6	No	Ramp Slope RT (%)	10.2		
Yes	Ramp XSlope LT (%)	1.1	No	Ramp XSlope RT (%)	3.4		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
			N/A	Curb Slope (%)	11.2		
qour by							





