

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15747	Main Street: PRESSLEY_RD			Cross Street: ROSE_THORN_PL			Location:	NE		
ADA ID: 246239F7D223	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	37.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
6 9 6 6	1 die wath	Possible Solutions:		Compliance Description			Data Compliance Description			
	N Y	Remove & Replace Entire Ram	<b>D</b> .	N/A	Ramp Length (in)	44.0	N/A	Grade Break?	N/A	
			P -	Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0	
and a set of the				No	Ramp Slope (%)	10.2	N/A	Grade Break XSlope (%)	0.0	
1 10 10				No	Ramp XSlope (%)	7.2				
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	19 1 2			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	A State and			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
* Internet A	Ro.	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
a little		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	1 AS 1 1 1	·····, ·····		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	10 15-1			N/A	Gutter Lip Ht (in)	2.0	N/A	Gutter X Slope (%)	N/A	
E C	2 + V			N/A	Painted X Walk1?	No		Road Slope (%)	3.3	
Street 1 Name	ROSE THORN PL				X Walk 1 Direction	To S		Road X Slope (%)	1.1	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.1	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	11.6	

