cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14159	Main Str	eet: LAWRENCE_ORR_RD	Cross	Street:	SUN_RAY_CT			Location:	W
ADA ID: 2560D7F35803				nitial Pass/Fail: Fail Overall Compliance: No					12.5
	Codes/Mitigation Info							nent Compliance	
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	with	N/A	Ramp Length (in)	24.5	No	Ramp Slope (%)	8.4
		Two New Directional Ramps or Equivalent.	-	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second s				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
SUM D	9			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SUN RAY OF	5 C C			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
All In		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
े हि	R ALT	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and the start of	B. S. A.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E A Find				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	With the state of			N/A	Shared Landing?	N/A			
	A 68/1-4	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	The second second	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the state of the	1 march m			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
2 . Jon III	A TOTAL				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LAWRENCE ORR RD	-			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	4.8
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	1.5
Street 2 Name	SUNRAY CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.5	N/A	Clear Space?	N/A
					Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

115- 5