

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13985	Main Street: CAMDEN_RD			Street:	EAST_BV	Location:	SE		
ADA ID: 25EBD6F45C74	EBD6F45C74 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description Data			Compliance Description		Data	
a la the second		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	89.0	No	Ramp Slope (%)	10.5
6 A A A A A A				Yes	Ramp Width (in)	74.0	Yes	Ramp XSlope (%)	1.8
WISST COL	A			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 ma	8		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the bar	K CAN			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A B	and a se	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	a have	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
3 / R. A. C. F. M.	Mar 1			N/A	Shared Landing?	N/A			
a dilling a fi	11/100	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 the main state of the second		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Y			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
A life line - M					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
31 MAN Store, Suit	A PA			N/A	X Walk 1 Width (in)	144.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	EAST BV				X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

Surface Condition? (G/P)

Good