



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10247	Main Street: BURTON_ST	Cross Street: WHISNANT_ST	Location: W
ADA ID: 2615878FC78A	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	49.0	N/A	Ramp Length RT (in)	50.0
			Yes	Ramp Width LT (in)	55.0	Yes	Ramp Width RT (in)	56.0
			Yes	Ramp Slope LT (%)	0.9	Yes	Ramp Slope RT (%)	7.2
			No	Ramp XSlope LT (%)	3.0	No	Ramp XSlope RT (%)	5.5
			N/A	Ramp Length (in)	59.5	No	Ramp Slope (%)	10.8
			No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	4.8
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	LT RP < 5%		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	PROW/ADA:		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
			Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A		Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstruction?	N/A	
						Obstruction Type	N/A	
								N/A
						N/A	Storm Grate/Utility Hazard?	N/A
							Storm Grate/Utility Type	N/A
								N/A
			Yes	Surface Condition? (G/P)	Good			
				Curb Slope (%)	45.4			