cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23615	on ID: 23615 Main Street: COLONY_RD			Cross Street: MANHEIM_CT				SE
ADA ID: 266589BDF28F	Ramp Type: BlendTrans2			itial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	0.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance				
	MANUTERIA ST	Possible Solutions:	Com	Compliance Description Da		a Compliance Description		Data
		Remove & Replace Curb Ram	/ith N/A	Ramp Length (in)	74.0	Yes	BlendTrans Slope (%)	0.1
		Two New Directional Ramps or	Yes	Ramp Width (in)	52.0	No	BlendTrans XSlope (%)	4.7
		Equivalent. Remove & Replace Gutter.	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
			N/A	Flare Slope LT (%)	-	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
AND STRANT			N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
E 8 Min			N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
		N/A	N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
		N/A	N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
			N/A	Shared Landing?	No		BWG Glisse (III)	1.0
		PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.5
			Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.0
	a line the	Not Found, R304.5.3	N/A	Painted X Walk1?	0.0 No	-	Painted X Walk2?	S.U No
	the state		N/A	X Walk 1 Direction	-	N/A	X Walk 2 Direction	-
E. E.					To N			To W
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	MANHEIM CT			X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	3.7
Stop Condition-Street 1	StopSign			X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	1.1
Street 2 Name	COLONY RD		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None			Road Slope (%)	3.8		Clear Space?	Yes
				Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 39	50.00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.0