

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                        |                              |                        |
|------------------------|------------------------|------------------------------|------------------------|
| Intersection ID: 25177 | Main Street: CARMEL_RD | Cross Street: MEADOWRIDGE_DR | Location: N            |
| ADA ID: 26CB234B1776   | Ramp Type: ParaDiag    | Initial Pass/Fail: Fail      | Overall Compliance: No |
|                        |                        | Severity Score: 12.5         |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**LT RP < 5%**

PROW/ADA:

**R304.3.2**

|                         |                |
|-------------------------|----------------|
| Street 1 Name           | MEADOWRIDGE DR |
| Stop Condition-Street 1 | StopSign       |
| Street 2 Name           | CARMEL RD      |
| Stop Condition-Street 2 | None           |

Total Cost: \$ 3200.00

| Compliance | Description          | Data  | Compliance | Description                 | Data  |
|------------|----------------------|-------|------------|-----------------------------|-------|
| N/A        | Ramp Length LT (in)  | 49.0  | N/A        | Ramp Length RT (in)         | 70.0  |
| Yes        | Ramp Width LT (in)   | 58.0  | Yes        | Ramp Width RT (in)          | 58.0  |
| Yes        | Ramp Slope LT (%)    | 2.9   | No         | Ramp Slope RT (%)           | 9.1   |
| Yes        | Ramp XSlope LT (%)   | 1.6   | Yes        | Ramp XSlope RT (%)          | 1.4   |
| N/A        | Landing Length (in)  | N/A   | N/A        | DWS Provided?               | N/A   |
| N/A        | Landing Width (in)   | N/A   | N/A        | DWS Contrast?               | N/A   |
| N/A        | Landing Slope (%)    | N/A   | N/A        | DWS Length (in)             | N/A   |
| N/A        | Landing X Slope (%)  | N/A   | N/A        | DWS Full Width?             | N/A   |
| N/A        | Landing Curb? (Y/N)  | N/A   | N/A        | DWS Offset (in)             | N/A   |
| N/A        | Shared Landing?      | N/A   |            |                             |       |
| N/A        | Gutter Ponding?      | N/A   | N/A        | Gutter Slope (%)            | N/A   |
| N/A        | Gutter Lip Ht (in)   | N/A   | N/A        | Gutter X Slope (%)          | N/A   |
| N/A        | Painted X Walk1?     | No    | N/A        | Painted X Walk2?            | No    |
|            | X Walk 1 Direction   | To SW |            | X Walk 2 Direction          | To SE |
| N/A        | X Walk 1 Width (in)  | N/A   | N/A        | X Walk 2 Width (in)         | N/A   |
|            | X Walk 1 Slope (%)   | 1.8   |            | X Walk 2 Slope (%)          | 3.5   |
|            | X Walk 1 X Slope (%) | 5.5   |            | X Walk 2 X Slope (%)        | 0.8   |
| N/A        | Ramp inside XWalk1?  | N/A   | N/A        | Ramp inside XWalk2?         | N/A   |
|            | Road Slope (%)       | 4.1   | N/A        | Clear Space?                | N/A   |
|            | Road X Slope (%)     | 2.9   | N/A        | Clear Space to XWalk (in)   | N/A   |
| N/A        | Any Obstructions?    | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A   |
|            | Obstruction Type     |       |            | Storm Grate/Utility Type    |       |
|            |                      | N/A   |            |                             | N/A   |
|            |                      |       | Yes        | Surface Condition? (G/P)    | Good  |
|            |                      |       | N/A        | Curb Slope (%)              | 8.4   |

